## Product Sheet 18.05.2024





Description	optional: 2 holders for lateral vices
Model	HAsyn
	11000
ID	41209

equipping the school workbench with two holders for each detachable lateral vice under the tray, holders of beech plywood. During the storage, the greased metal pliers guides are housed. Mounting under the tray.

Changes and errors reserved. Illustrations similar.